BRIEFING NOTES FOR D1006, L2331

Pay careful attention to page T4, T1.1 Tender notice and invitation to tender as the most important information is highlighted there.

Pay special attention to all the pages that contain this heading -

Failure to complete, sign and date this form or failure to acknowledge receipt of each Addendum issued or failure to return with the quotation submission a complete copy of each Addendum issued shall result in the quotation being considered non-responsive in terms of subclause F.3.8 of the Conditions of Tender and such a quotation shall be rejected.

If this heading is displayed and a contractor feels that it is N/A and does not sign the page, the tender will be non-responsive. The content may be marked as N/A if so applicable as is generally the case with Page T13 but the Bidder must still sign and date the required spaces as instructed. Please note initialling the bottom of the page is not seen as a signature it is simply acknowledging that the bidder has seen the page and is aware of what is in his/her document.

Page T14 must be completed in full. Pay special attention to the highlighted sections-

SUPPLIER COMPLIANCE STATUS	TAX COMPLIANCE SYSTEM PIN:	OR	CENTRAL SUPPLIER DATABASE No:	MAAA	
B-BBEE STATUS LEVEL VERIFICATION CERTIFICATE	TICK APPLICABLE BOX	B-BBEE STATUS LEVEL SWORN AFFIDAVIT		(TICK APPLI	CABLE BOX]
	☐ Yes ☐ No		☐ Yes	□ No	
POINTS FOR B-BBEE] ARE YOU THE ACCREDITED REPRESENTATIVE IN SOUTH AFRICA FOR THE GOODS /SERVICES /WORKS OFFERED?					
REPRESENTATIVE IN SOUTH AFRICA FOR THE GOODS /SERVICES /WORKS	□Yes □No	BA	E YOU A FOREIGN SED SUPPLIER FOR THE DODS /SERVICES	□Yes	□No

Are you a foreign based supplier – This answer should generally be No and the bottom section (

QUESTIONNAIRE TO BIDDING FOREIGN SUPPLIERS

) does not need to be completed as the contractor has already indicated that he is not a foreign based supplier.

T15 must be completed and signed thus accepting the terms for bidding.

SBD 4, 8 and 9 are extremely important and failing to answer all the questions as required also lead to a bidder's offer being non-responsive. This has occurred on numerous occasions.

SBD 6.1 Note 6.1 must be completed to claim BBBEE Points. It should be completed as follows:

B-BBEE Status Level of Contributor: 1 (As the BBBEE level the bidder's certificate or affidavit grants)

= ...20 (Correlating points to level – see table 4.1) (maximum of 20 points)

SBD 6.2 is not applicable to this Contract as there is no imported items.

Returnable D - page T35, Generally the simplest and most frequent submission is a Sworn Affidavit. It should be noted that an affidavit must be an original that is certified by a commissioner of oaths. If a copy is submitted the contractor will not be awarded any preferential points and therefore lose out on 20 points. On the Affidavit one question is regarding the financial year for which the affidavit is done. This must be the latest financial year and not older than 12 months from date of closing of the bid, but also this time cannot be in the future, e.g. February 2022. All provisions for disclosing information under Oath must be complied with to ensure the affidavit is acceptable. For BBBEE certificate – these must be submitted as a copy – no need of certification.

Returnable E - page T36 must be completed and signed by all members/directors. If one of the members/directors fails to sign it is seen as a non-responsive document due to the directors/members not being aware of the tender submission. Also ensure that the specimen signature does appear on the resolution letter of the company owners attached to this returnable.

Returnable G - page T38 must be completed and have CV's attached as is indicated at the top of the Page. G2 has been redacted and it is not necessary to complete this section.

Returnable J - page T43 Must be signed, dated and completed as indicated on the bottom of page T44. Please follow the instructions on page T43 on how to calculate the minimum labour percentage and note that the specified minimum labour percentage is 4% as indicated. While tendering below the minimum is no longer a disqualification criterion, a penalty would apply to the bid if awarded for not achieving the minimum target.

Returnable K - page T45 Must be completed correctly and signed. This should be read and completed accordingly. Question 3 has three sub headings. Generally, the contractor will answer yes to only one of these. The corresponding number in question 4 must then also be completed. Example – If 3(a) is answered yes then the contractor must answer 4(a) as well, If 3(b) then 4(b) etc

Page C3 as the form of offer must be signed and the amount in words must be completed failure to do this will invalidate the tender.

Please check that the amount on C3(For of Offer) and C39(BOQ Summary) match.

On a contractual note the following must be mentioned:

The construction period is 6 months and failure to complete the project within the specified timeframe will result in penalties. It is of extreme importance that these risks be factored into the pricing of the documents as the bidders' price is also compared to realistic market value of the works that has been assessed by a third party to guide if the quoted price is reasonable.

C4.1 LOCALITY PLAN

District Road 1006 is located to the far East of the Table Mountain area. Access to this road can be achieved by travelling on P25-1 from Mountain Rise for approximately 4 KM before turning onto P26. Once one joins P26, one will need to travel 24 KM before reaching the P423 turn off. Once on P423, one will need to travel 6.5 KM to reach the start of D1006. The location of the road can be seen in figure C4.1.



Figure C4.1 – Locality Plan of District Road D1006

The approximate limits of construction can be seen in Table C4.1.

Table C4.1 - Approximate Start and End co-ordinates of D1006

<u>Km</u>	<u>Latitude</u>	<u>Longitude</u>
D1006 Km 0.00	29,58099°S	30,67516°E
D1006 Km 5.70	29,59413°S	30,71475°E

PROJECT BACKGROUND

WARD: 6

TRIBAL COUNCIL: Gcumisa Traditional Council

FACILITIES AND SERVICES ALONG THE ROAD: dwellings

TERRAIN: Mountanious

CONDITION OF THE CURRENT GRAVEL ON THE ROAD: loss of gravel and drainage problems.

ROUTE TO THE QUARRY : quarry is on the road at km 2


Average distance to the quarry is 2km.

Please see the photos below for some images of the roads condition and the borrow pit.

Quarry for D1006



Road conditions on D1006



Local Road 2331 is located to the far East of the Table Mountain area. Access to this road can be achieved by travelling on P25-1 from Mountain Rise for approximately 4 KM before turning onto P26. Once one joins P26, one will need to travel 24 KM before reaching the P423 turn off. Once on P423, one will need to travel 17.5 KM to reach the start of L2331. The location of the road can be seen in figure C4.2.




Figure C4.2 – Locality Plan of District Road L2331

The approximate limits of construction can be seen in Table C4.2.

Table C4.2 - Approximate Start and End co-ordinates of L2331

<u>Km</u>	<u>Latitude</u>	<u>Longitude</u>
L2331 Km 0.00	29,50122°S	30,69686°E
L2331 Km 2.20	29,51402°S	30,70747°E

PROJECT BACKGROUND

WARD: 8

TRIBAL COUNCIL: Gcumisa Traditional Council

FACILITIES AND SERVICES ALONG THE ROAD: dwellings

TERRAIN: Rolling


CONDITION OF THE CURRENT GRAVEL ON THE ROAD: loss of gravel and drainage problems.

ROUTE TO THE QUARRY: from L2331 you take a left into P423 for 1 km than take a right into D661, proceed for 2 kms and the quarry will be on your left.

Average distance to quarry is 3km.....

Please see the photos below for some images of the roads condition and the borrow pit.

Quarry for L2331 (on L662)



Road conditions on L2331

